

# SOUTH PRODUCTION NOTES

Feb 9, 2016  
3-11 Shift Notes

## **BASF EMPLOYEES**

72 Last Recordable  
140 Last Lost time

**SAFETY Notes:** Check the walkways for ice and treat with icemelt. Need to remind operators that Styrene material on line #2 can't be washed down the drain. Building 31 sump currently shut off. We had a false alarm on the fire system in bldg 16. System status is currently displaying "not normal" – WOW.

**Title V Notes:** Trimer –tank 2 ORP probes were worked on Friday – keep an eye on them. The chem tank ORP probe still isn't reading correctly.

CTO – CTO is running but the valve still needs to be fixed. Keep an eye on the system. #3 is currently running to CTO.

F-1 Scrubber – Continue sampling of scrubber and sump in building 31. Sump was sent to WWTP on afternoon shift.

### **#1 MED / D 1780: Priority #1**

We are not going to run until the load cell is fixed. Possibly this sometime Wednesday. We are switching #3 line to D1780. This is a very high priority as it is going to be supplying the Old Pfaudler and #6 calciner.

When we start do not increase the speed on the extruder to above 60 hz until IMC can correct the issue. Still need low level probe on miners installed.

### **#1 RC / D 1780:**

Once we have calciner 3 up and going please run the hopper completely empty and start clean up.

**Feed in batch order and fill out calciner feed sheets.**

### **#2 MED line / Styrene: Priority #2**

Started line back up and made batches. Continue with Justin's approval.

There are drums of wet mix. There are also several drums of material that will need to be refed through the dryer – do not feed this material until instructed to.

**Need to remind operators that Styrene material can't be washed down the drain.** The new mixer plows should be in the week of the 2/29.

### **#2 RC/ Styrene:**

Finished refires. Will need to communicate with Justin as to fire the batches made today.

Continue to keep an eye on the liners in the bags; have had few instances where it falls in. The Floor CRT will need to take a sample out of the F1 scrubber and the sump in building 31 to wastewater. Before unlocking building 31 sump WWTP will test these samples for moly and if the sump is low, we can unlock and send to WWTP. At all other times the west sump will remain locked out.

**Need to remind operators that Styrene material can't be washed down the drain.**

The new mixer plows should be in the week of the 2/29.

### **#3 MED line / D-1780:**

GEM repaired valve today. Continue to make batches of D 1780.

Make sure we are greasing end seals.

**Please keep a close eye on the ammonia and nitric additions.**

### **#3 RC / D 1780:**

Will need to set up discharge for D 1780. We will continue to run the D 1780 on #3 Calciner. Calciner is lit and coming up to temp.

**Feed in batch order and fill out calciner feed sheets.**

### **#4 RC / D-0222 Cleaning:**

We need to switch up the screener again. The over size is to be changed to a .065" x 1/4" per Grodecki. Then we will have to rescreen the bags we remade last night.

Keep an eye on the samples and amount of fines coming off the calciner.

We will need to remake and resample the bags.

We still need fish labels – may be in Calvins area in the stores.

We will take the 1<sup>st</sup> 1/2 drum and haz-waste due to possible contamination.

### **#5 RC / Catoxid:**

Continue feeding. **We need to make sure that pallets of Catoxid are clean after they are full. We cannot load them out dirty.**

We will need to look at the DC every hour for the readings sheet.

DC gauges are working at the dust collectors. For some reason the control room screens are not reading correctly. Kirk has been notified.

**Do NOT fill hopper all the way up due to blowdowns turning on and overflowing the hopper.** It should not be filled past 2ish feet below the top to allow room for blowdowns.

2 bags of wet material to wait for engineering – don't feed now.

Continue to monitor 5A after filter. The log sheet is in the 2<sup>nd</sup> floor MCC room bldg. 11 - needs to be filled out every 2 hrs.



### **#6 RC & Dryer / D-0761:**

Fines have been weighed. Clean up has been started continue.

Cleanup sheet is in the GL office, screener needs to be changed over. The fines screen has been cleaned, but is stained with Styrene.

There is a check weigh scale located in the middle of building 27. Please check weigh all drums.

### **West Pfaudler / D- 0222:**

Two batches were made on midnight shift. Continue as manpower allows.

Only lot 187/188 is OK to use. **Do not use any other lots.**

Keep an eye on tank 7, See email about using the auto steam valve working on one of the stations in the control room.

AI 3945 Lot 187 and 188 are in pass.

### **East Pfaudler/ D-0761:**

MOD is in control room. Lid has been replaced and clean up is finished.

### **6 Tank: Tank empty**

Valve fixed. There was a screen and band clamp in the valve.

### **7 Tank: D-0222 Solution**

Maintain tank at 50 deg. Will need to monitor and adjust steam. Auto valve is supposed to be working on the computer #868 only. See email on CRT desk

### **National Dryer / D-0222:**

Continue to feed batches as material is available.

### **PK Blender / Catoxid:**

Continue. Transfer pump was fixed on afternoon shift.

Watch DC closely. We have added a row of bags and replaced some of the other bags. Need to ensure that the DC is in range before starting.

Level indicator is working on Chrome tank.

**Need to make sure that the building is being cleaned up!**

Dust collector can be blown down by switching the magnahelic gauge to 0 and then shutting off the blower when it starts to blow down. We need to install another row of bags in the DC when able. DC gauge has been added to

Wonderware and has been moved over to near the weight tank. Gauge should be set at 3.5 and 4.25.

### **Abbe Blender / D 5206:**

**HF tote has been closed up and Abbe lid was remove and vessel cleaned out. Cover plates over open hole in floor have been reinstalled.**

**Tower 3 / Cu-0860:**

**Tower loaded.**

**Tower 6 / Cu-0860**

**Tower loaded.**

**North Screener /Cu-1155:**

**Screener is set up for Cu-1155.**

**South Screener /Cu 0860:**

**South Screener is set up for 0860. Did some testing. Plan to run on second shift Tuesday.**

**#2662 (west) Pill Machine /**

**Back together and holding.**

**#2664 (east) Pill Machine /**

**Back together and holding.**

**TK #2 / Zr-0404:**

**Out of material for now. Just unloading. Two bags of lot 71 that are over by the lab are still not in pass.**

**When we are done feeding the current lot we will stop feeding until more pills can be made.**

**TK #4 / Cu-2508:**

**Getting kiln lit on day shift. Please start bringing kiln up to temp. Plan on starting to load on Wednesday afternoon.**

**Need to inspect area before calling EHS to inspect.**

**Harrop Kiln / Al-4196:**

**Waiting on parts for the regulators. Elliott may need to finish the burner tuning. Saggars have been switched out and are ready for next run.**

**Building 27 Belt Filter / Cu-6081:**

**DL Page completed their work on the dryer chamber. Holding for more material/start up orders. We have switched to 188 lined super sacks. These will need cardboard sleeves around them.**